05-Feb-18 10:24:29 PM ANALYSIS OF CASH FLOW

	THE TOTAL OF THE												
	BEGINNING CAPITAL RESERVE FUND BALANCE ADDITIONAL RESERVES BASED ON ANTICIPATED ABILITY EXPENDITURES:		2018 \$596,094.00 \$210,000.00	\$609,860.00 \$210,000.00			\$285,696.00 \$210,000.00		2024 \$ 378,881.00 \$ 210,000.00		2026 \$771,006.00 \$210,000.00	\$ 9	2027 228,481.00 210,000.00
Appliance													
	Icemaker RefridgeratoR												
Asphalt a	and Concrete												
	Asphalt Maintenance Asphalt Crackseal, Seal Coat and Repairs Lot -A1 Asphalt Crackseal, Seal Coat and Repairs Lot -A2 Asphalt Crackseal, Seal Coat and Repairs Lot -B Asphalt Crackseal, Seal Coat and Repairs Lot -C Asphalt Crackseal, Seal Coat and Repairs Lot -D				\$ 2,047.00 \$ 2,017.00 \$ 2,199.00	\$ 9,293.00 \$ 2,815.00		\$ 2,815.00		\$ 2,047.00 \$ 2,017.00	\$ 10,795.00 \$ 2,815.00		
	Asphalt Crackseal, Seal Coat and Repairs Lot -E Asphalt Overlay Lot-A1 Asphalt Overlay Lot-B Asphalt Overlay Lot-B Asphalt Overlay Lot-C Asphalt Overlay Lot-D		\$ 15,500.00		\$ 2,199.00		\$ 16,000.00			\$ 2,199.00	\$ 32,890.00	\$	37,367.00
Dalaasia	Asphalt Overlay Lot-E Brick Walkways Walkway Retaining Walls	Repairs next 2 ye	\$ \$ 85,000.00 \$ 10,000.00	\$ 85,000.00		\$ 22,030.00							
	s and Decks Balcony support repairs Pool Deck Resurface Pool Deck Reseal					\$ 5,808.00				\$ 6,548.00		\$	779.00
Doors	Garage Door Replacement												
Electrical	Storage Door Replacement Il and Plumbing						\$ 4,000.00					\$	3,476.00
	Electrical - Major Repairs or Replacement Plumbing - Boiler Replacement	HVAC Clubhouse	\$ 2,000.00 \$ \$ 43,000.00		\$ 2,000.00		\$ 2,000.00		\$ 2,000.00		\$ 2,000.00		
Electroni	Plumbing - Major Repairs or Replacement ics		\$ 2,000.00		\$ 2,000.00		\$ 2,000.00		\$ 2,000.00		\$ 2,000.00		
Fencing	Fire Alarm System Replacement											\$	34,760.00
Flooring	Fencing - Metal - Phased Replacement				\$ 10,922.00								
riconing	Carpet Placement - Clubhouse Vinyl Tile Replacement - Clubhouse	Luis/Jim discuss Laundry room - A	\$ 3.919.00	\$ 15,000.00									
Furniture													
Gutters a	and Roofing Gutters and Downspouts - Clubhouse Gutters and Downspouts - Units Roofing - Garage Storage Area Roofing - Clubhouse Replacement Roofing - Flat Recoating Roofing - Pool Building Replacement			\$300,000.00			\$ 50,000.00	\$250,000.00					
HVAC	Roofing - Unit Refurbishment		4 05 000 00	\$ 300,000.00				\$230,000.00					
Irrigation		Review cost	\$ 25,000.00										
Lighting	Backflow Preventers Irrigation Controllers Replacement												
	Bollards Parking Lot Fixtures Storage Area Fixtures Unit Exterior Fixture Replacement	Includes ALL fixtu	ıres	\$ 30,000.00									
Painting a	and Repairs Clubhouse Interior Metal Components Stucco - Storage Buildings Wood - Gazebo Repairs - Buildings Repairs - Stucco Units	Cracking - stucco		\$225,000.00	\$225,000.00							\$	4,939.00
Pool and													
	Pool Filter - Replacement Pool Heater - Replacement Pool Lift - Replacement				\$ 1,532.00 \$ 3,501.00				\$ 1,532.00				
	Pool Resurfacing Pool and Spa Pump Replacement Spa Filter Replacement Spa Heater Replacement Spa Replacement			\$ 6,000.00							\$ 2,025.00		
Renovati	ion <u>Clubhouse Refurbishment</u> <u>Gazebo Replacement</u> Pool Restroom Refurbishment		\$ 5,000.00						\$ 9,532.00				
Signage	Metal Replacement Wood Replacement		\$ 2,000.00		\$ 2,000.00								
	TOTAL EXPENDITURES		\$ 196,234.00 \$ - \$ -	\$661,000.00 \$ - \$ -	\$ -	\$ -	\$ -	\$252,815.00 \$ - \$ -	\$ 15,064.00 \$ -	\$ -	\$ -	\$ \$ \$	81,321.00
	PROJECTED INTEREST Profit				\$ -	\$ -	\$ -		\$ -	\$ -	\$ -		